

LINK 410/510/530

Release notes for firmware version: 9.5.5103
September 2019



Why should the LINK 410/510/530 be updated?

We always recommend that you install the latest application on your LINK 410/510/530 before installation to benefit from the latest software development.

What features have been added or improved?

Change trip mode after a firmware update

Fixed an issue that caused the trip mode to switch to **Business** after a firmware update instead of keeping the current trip mode.

LINK switches in Working Time mode automatically to business

Fixed an issue that caused the LINK to switch to **Business** mode after it has been used in Working Time mode with position suppression enabled.

Driver login with PRO 2020 when digital tachograph is connected

When no driver card is inserted in to the digital tachograph, the PRO 2020 will now support driver registration using RFID card scans.

General Improvements

Various other improvements and bug fixes have been implemented in this firmware version.